


1936 B Original Magneto Model WICO AP



The owners manual states that “More damage is done to magneto through over oiling than from a lack of oiling. The Owners manual further states you should fill the oiling ports every 500 Hours, while the manufacturers stamped instructions read every 200 hours. You can see the design evolution towards the WICO X and WICO C began with the AP .